

Porsche 944 951 968 Spare Parts and Cross Reference

18.02.2014

NEW ITEM

Part	Clarification	MY	Other cars	Manf. Part #	Porsche #	€ Manufacturer / Other
Fuel pressure regulator	FPR, 2,5bar	944/951 85.5-89		0 280 160 227	944 110 198 04	100€ Bosch
Fuel pressure regulator	FPR, 3bar	951 85.5-89	BMW 325 E30 85-91	0 280 160 258		100€ Bosch, for chipped car
				0 280 160 249		100€ Bosch, for chipped car
Fuel pressure regulator	FPR, 3,8bar	S2/968		0 280 160 287		Bosch
MAF Mass Airflow		968	Audi 80 Avant 91-96	0 280 213 017	951 606 125 01	Bosch VAG 034 133 471 N
Cut-Off Valve / BOV / Bypass		951	Saab 9-5 (part# 4441895)	0 280 142 110		30€ Bosch
Cut-Off Valve / BOV / Bypass		951	Newer Audi / VW	0 280 142 115		49€ Bosch
Air filter		944 82-89	VW Corrado 1.8 16V 4/89-7/92			6€
Radiator fan switch	3-pole 95°-85°+102°-92°C	82-91	Audi 100 88-94 Seat Ibiza 93-94 VW Golf II 85-91 Volvo 400-s	7.5635		Facet
Expansion tank cap	17mm/15lbs	82-85.0	Alfa 33 1,7-16V 87-92 Audi 100 67-78 Ford Granada 2,5-Diesel			
Throttle position sensor		944 82-89		0 280 120 308	944 606 113 01	Bosch

Porsche 944 951 968 Spare Parts and Cross Reference

Throttle position sensor		951	Volvo 440 1.7 Turbo 9/87-7/91	0 280 120 400	951 606 113 00	Bosch
Throttle Position sensor		968	Alfa 145 / Saab 9000 Volvo 480 E/L 960 90-94 Volvo 960 2.0 8/90-9/93	0 208 122 001/4	944 606 116 00	Bosch
Crank pilot bearing				6202-2RS/C3/FAG		FAG
DME temperature sensor	DME, blue M12x1,5	82-91 968	BMW 316i Fiat Uno Fire-ie/Turbo/ie Opel Astra 8V injection Volvo 700-s Turbo -84	0 280 130 026	944 605 125 00	Bosch
Knock sensor		951, 944S, 944S2 968	Ford Escort 1.6 80-85 Citroen BX 19GTi 16V 87-93 Saab 900i-16V 85-93	0 261 231 006		Bosch
Speed / Reference sensors	Speed / Ref. Sensors	82-91 968		0 261 210 003		8v 2pce, 16v 1pce
Thermostat	83°	82-88		G4000-23460 234-82 1026-80		Wahler Motorad Vernet
Thermo-pneumatic valve		951	Audi 100 77-91	058 131 851 A	058 131 851 A	
Idle control valve, ICV		944/951 85.5-89	Peugeot 405 1,9GRi Renault R19 1,7iKat Renault Clio-I 16V-1,8/2,0 Volvo 740 B200ET/230ET -87	0 280 140 501		Bosch
Idle control valve, ICV		S2		0 280 140 531		Bosch
Idle Control Valve		968		0 280 140 536		Bosch

Porsche 944 951 968 Spare Parts and Cross Reference

Cooling hose	951	Peugeot 205 D/1,6/1,9 waterpump		951 106 239 01	
Oil filter	82-91	I	OC142	944 107 201 90	Knecht / Mahle, orig.
			OC75		Knecht / Mahle, longer
			W719/22		Mann
			H 14 W 25		Hengst
			R 128		Tecnocar
			FT 5239		Fiaam
			PH-6941		Fram
	968		0 451 103 213	944 107 201 08	Bosch
Fuel system and exhaust					
Oxygen sensor, lambda	85.5-91		0 258 003 012	951 606 135 0	Bosch
Oxygen sensor, lambda	968	Alfa 155 92-97 Audi A4 B5	0 258 003 011	944 606 135 02	Bosch
Fuel pump	944 85.5-88, S/S2	Alfa 75 1,8 Turbo 87-89 Fiat Uno Turbo-1,3ie/1,4ie 85-92 Renault Espace 2,0i/2,2i/2,8i 91-96 Volvo 343 B19E/B200E/B200F	0 580 464 028	944 608 102 06	Bosch, green
Fuel pump	944 82-85.0, 951		0 580 464 021	944 608 102 04	Bosch, blue
Fuel filter	<u>M14 threads</u> 82-91	BMW 320i 4.79-82 BMW 323i 9.78-8.79 BMW 518i 75-79			
Fuel tank cap	82-91	Audi, Passat, Golf I			

Transmission

Porsche 944 951 968 Spare Parts and Cross Reference

Clutch master cylinder gasket	82-91		PBR K7664X	
Clutch slave cylinder gasket	82-91	MB W123/124 (FAG) 76-95	PBR 1021S	Has to be modified slightly

Front axle and steering

Balljoint, lower	Steel control arm	82-85.0	VW Golf I	12€
Control arm	Steel control arm	82-85.0	VW Golf I	23€
Shock absorber cover rubber		82-85.0	BMW 316/318/320 E21 75-82 front Mercedes Benz W124 front Nissan Sunny N13/B12 rear VW Golf 73-91	
Wheel bearing, front		82-86		VKBA 1400 SKF
		87-91		VKBA 956 SKF
	Outer	87-91	L68149 99402 L68111	Timken
	Inner	87-91	1-M12649 1-M12610	Timken
	Sealing	87-91	ERIKS RST 45 62 10	
Powersteering belt	L=950mm	82-91	Audi 80 1,3-1,8 86-92 LA/VP Honda Civic 1.2/1.3 80-83 LA/VP Seat Toledo 1.6-2.0 -93 LA VW Golf 1.6/1.8 86-91 LA Opel Vectra B TurboD-1,7 96- OT	

Porsche 944 951 968 Spare Parts and Cross Reference

Tie rod, outer	Powersteering	82-86	Golf I, Jetta I, Caddy I	171 419 812	944 347 333 00	TRW
	Manual	82-83 94DN402644 until		116 020 3226	944 347 333 00	Meyle
				10251	944 347 333 00	Lemförder

Rear axle

Wheel bearing, rear	82-85.0	VW beetle 1302/1303	VKBA 592	SKF
	85.5-91		305988	SKF
			527243BE	FAG
Rear control arm	82-85.0	VW beetle 1302/1303		
CV joint	82-86	VW Transporter 68-90, Syncro 85-90		couple mm wider
CV joint cover rubber	82-91	VW Transporter 68-90, Syncro 85-90		
	82-91	BMW 700		

Wheels and brakes

Brake caliper seals	Front	944 82-89	Audi 100 5E-2.2/TD-2.0 1977-7.79	ATE
			Peugeot 505	
			Peugeot 604 front	
Brake caliper piston	Front	944 82-89	Peugeot 504 78-82 front	ATE
			Peugeot 505 front	
			Peugeot 604 front	
Brake master cylinder		82-91	MB W123	
Emergency brake shoes		82-91	BMW e28 525i 81-88	Re-use old springs

Handlever

Porsche 944 951 968 Spare Parts and Cross Reference

system, pedal cluster

Brake and clutch pedal pad	85.5-91	Golf II
----------------------------	---------	---------

Body and interior

Sun visor clip	82-91	Golf III	3B0 857 561 BY20	Grey
			3B0 857 561 BB41	Black
			3B0 857 561 B8YS	Beige
Sun visor cover-clip	82-91	Golf III	3B0 857 563 BY20	Grey
			3B0 857 563 BB41	Black
			3B0 857 563 B8YS	Beige

Electrical equipment

Battery	64Ah	82-91	Audi 100, gasoline 75-90 Seat Ibiza, 93-98 VW Golf III, gasoline	
DME-relay		82-91	Opel	4RP 008 189-051 Hella
Headlamp		82-91	Audi 80 5/75 – 7/76 VW Golf I VW Passat 5/73 – 7/77	20e
Voltage regulator	115A alternator	82-91	Audi 100, 81-92 BMW 300s, 81-90	1 197 311 040 Bosch

Porsche 944 951 968 Spare Parts and Cross Reference

			Ford Sierra, 82-93 VW Golf 8.81-91	
Alternator	90A	82-85.0	Ford Scorpio 2,0-OHC/Diesel/TurboD 90A Ford Sierra 1,3-2,0 OHC 90A	
Alternator	115A	85.5-91		0 120 468 005 Bosch, or 0 120 468 004
Alternator brushes	5x8x15mm	82-85.0	MB W123 76-80 VW Golf 74-7.81 Bosch Volvo 200-s 74-8.81	Bosch
Alternator brushes	5x8x19mm	85.5-88	BMW 300s 81-90 Ford Sierra MB W124 VW Golf 8.81-91	Bosch
Alternator sliding ring		82-85.0	BMW 300s 75-81 MB W123 76-80 VW Golf 74-7.81 Volvo 200-s 74-8.81	Bosch
Alternator sliding ring		85.5-88	BMW 300s 81-90 Ford Sierra MB W124 VW Golf 8.81-91	Bosch
Alternator belt	L=735	82-85.0	Peugeot 605 TD-2.1 -94 LA Rover 75 1,8 LA Rover Freelander 1,8 LA	
Alternator belt, cars with AC		82-85.0	BMW 535/540 E39 ilmastointi Mazda 626 1.6/2.0 85-87 LA/OT Toyota Carina E 2,0 -93 LA Toyota Picnic 2,0 VL/ei ILM	

Porsche 944 951 968 Spare Parts and Cross Reference

Alternator belt	6x725mm	85.5-91	Nissan Sunny GTI-16V 1,6/1,8 86-91 LA Nissan Bluebird 1.6-2.0 86-88 LA Nissan Prairie 2.0 88-89 LA			
Alternator belt, cars with AC	L=1005mm	85.5-91	Citroen Jumper 2,5D/TD/TDi LA+OT MB 208D/210D/308D/310D -95 LA MB 408D/410D -95 LA Peugeot Boxer 2,5D/TD/TDi LA+OT			
Windshield washer pump		82-91	VW Golf I/II/III			
Reverse light switch		82-91	MB 100D MB 207D-310D (601/602) 80-95 MB 407D-410D (611) 82-95			
Ignition coil		82-91 968	911/928/924/944/968	0 221 118 322	944 602 115 01	Bosch
Distributor rotor		944/951 (ei S/S2)		0 300 900 169	944 602 901 01	Beru (EVL 169)
Distributor Rotor		968		1 234 332 389	944 602 213 01	Beru EVL 174 Bremi 7031
Turn signal, side		82-91	Golf I / II			
Starter motor brushes			Audi 100			
Spark plug		944/951 82-91	Bosch WR7DC NGK BPR6ES			
Spark plug		S2	NGK BPR7ES			
Ignition control unit		944S/S2	Ford Escort 1,6i 86-90 Opel Corsa 1,2N/1,4 87 Saab 900i-16V 85-93 Seat Ibiza 1,5i			Bosch
Turn signal relay		82-91	Audi A6 BMW 316-320 9.79-90 Ford Sierra 82-93	0 335 200 041		Bosch

Porsche 944 951 968 Spare Parts and Cross Reference

		Opel Astra VW Golf III 91-98			
Distributor cap	944/951 (NOT S/S2)		1 235 522 325 0 330 920 414	944 602 251 00	Bosch Beru (VK 442 S)
Distributor cap	944S / S2	Volvo B200/230			
Distributor cap	968		1 235 522 395	928 602 211 01	Beru VK177s (0330920331) QUINTON HAZELL XD151
Distributor dust cover	82-89		1 230 500 219	944 602 803 00	Bosch
Ignition switch	82-85.0	Golf I / II 74-92			